

Potential Hazards	Preventative Measures	Remark
1. Drilling machine swing arm bucket attack to worker injury	- Banks man stand by during excavation all time.	
2. Machine oil leak to the ground.	- Machine must be inspection before used.	
3. Under ground equipment or cable were damage	- Inspect area excavation before start work	
4. Drilling machine fall down	- Outrigger standing for stable.	
5. Tire of drilling machine was blowout	- Tool box talk to drilling machine operator before start work.	
6. A Community,Cargo,Property were damage, injury	- Checked position of underground equipment and cable line before start work - Drilling machine operator must beware when working - Tire was inspection before start work. - Used water for spray protect dust.	

JSA Check Point

